


TUTORIAL SERIES FOR

Mastercam.X²

TUTORIAL 5

LEVEL 1 – 2D POCKET WITH ISLAND AT A DIFFERENT DEPTH, CIRCLE MILL AND CYLINDRICAL STOCK.



Mill X²

Objectives:

The Student will design a 3-dimensional wireframe drawing by:

- Creating arcs knowing the center points and the diameters.
- Creating a polygon.
- Creating an arc knowing the endpoints and the radius.
- Rotating the arc to complete the geometry.
- Creating fillet arcs.



The Student will create a 2-dimensional milling toolpath consisting of:

- Cutting a pocket with island at a different depth.
- Circle milling the 3" diameter hole.

The Student will check the toolpath using Mastercam's Verify module by:

- Defining a 3-dimensional cylindrical block the size of the workpiece.
- Running the Verify function to machine the part on the screen.

ALL DIMENSIONS IN INCHES



TITLE TUTORIAL 5

MATERIAL ALUMINUM T6061

DATE: OCT 12, 2006

eMastercam.com

Mill X²


GEOMETRY CREATION
Setting the toolbar states

To start a new file from Mastercam:

File

➤ **New**

- Before starting the geometry creation we should customize the toolbars to see the toolbars required to create the geometry and machine a 2D part. See **Getting started** page A-5 in the **User Notes**.
- **Toolpaths/Solids manager** to the left of the screen can be hidden to gain more space in the graphic area for design. Press **Alt + O** to remove it.
- Before starting the geometry make sure that the **Grid** is enabled. It will show you at each moment where the part origin is. See **Getting started** page A-5 for details.








STEP 1:

CREATE THE OUTSIDE & THE INSIDE ARCS KNOWING THE CENTER POINT AND THE DIAMETER.


Create

➤ **Arc**



➤ **Create Circle Center Point**



- Enter the **Diameter** value  9.0 (Enter).
- [Enter the center point]: Move the cursor to the center of the grid to select the **Origin**.
- Select the **Apply** button to remain in the same command. 
- Select the **Fit** button to fit the geometry to the screen. 
- Enter the **Diameter** value  5.0 (Enter).
- [Enter the center point]: Move the cursor to the center of the grid to select the **Origin**.
- Select the **Apply** button to remain in the same command. 


Select Origin



Mill X²

- Enter the **Diameter** value  3.0.
- [Enter the center point]: Move the cursor to the center of the grid to select the **Origin**.
- Select the **OK** button to exit the command. 
- The drawing should look as shown to the right.


- 💡 During the geometry creation of this tutorial, if you make a mistake you can undo the last step using the **Undo** icon. You can undo as many steps as needed. 
- 💡 If you delete or undo a step by mistake, just use the **Redo** icon. 



STEP 2: CREATE THE POLYGON.


Create

- **Create Polygon**
- Change the number of sides (#) to 6.
- Enter the **Radius** value.
- Enable **Corner** for the system to measure the radius to the corner of the polygon.
- [Select position of base point]: Select the center of the arcs as shown in the following screenshot.




- Exit the polygon command. 

Select the center here




STEP 3: CREATE AN ARC WITH A RADIUS OF 1.5 KNOWING THE ENDPOINTS AND THE RADIUS.

Create

- **Arc**
- **Create Arc Endpoints**
- Enter the **Radius**  1.5 (Enter).
- [Enter the first point]: Select the endpoint of the line as shown to the right.
- [Enter the second point]: Select the endpoint of the line as shown to the right.


Select the first point here

Select the second point here






Mill X²

➤ [Select an arc]: Select the arc to keep as shown.



➤ Select the **OK** button. 

STEP 4: DELETE THE CONSTRUCTION LINES.

➤ Select the **All** button.  |  | 

➤ Enable **Entities** and **Lines** as shown to the right.



➤ Select the **OK** button to exit. 


➤ Select the **Delete** entity icon. 

STEP 5: ROTATE THE ARC ABOUT THE ORIGIN TO COMPLETE THE PART.

Xform

➤ **Xform Rotate**


➤ [Rotate: select entities to rotate]: Select the 1.5 radius arc.



➤ Click on the **End Selection** button. 

Mill X²

- Make sure that you make all the changes as shown in the screenshot to the right.
- Change the Number (#) to 5 (Enter).
- Enable **Angle between**.
- Change the **Angle** to 60 degrees (Enter).
- If the **Preview** is active you should be able to see the result.



- Select the **OK** button to exit.

Screen

- **Clear colors**


STEP 6:

FILLET THE CORNERS.

Create

- **Fillet**
- **Fillet Chains**



- Enter the fillet **Radius**  0.25.
- [Select chain 1]: Select Entity A.



Select
Entity A

- Select the **OK** button to exit chaining.


- Select the **OK** button to exit the command.



Mill X²

STEP 7: TRANSLATE THE 5" DIAMETER ARC DOWN.

Select this arc



Xform

➤ Xform Translate

➤ [Select entities to translate]: Select the 5" diameter arc.



➤ Select the **End Selection** button.

➤ Enable **Move**.

➤ Set the number of translations to # 1.

➤ Change the **Delta** value on Z to -0.125.

➤ Select the **OK** button to exit.



Screen

➤ **Clear colors**

➤ Select the **Isometric View** from the view toolbar to see the stock.



Select the **Top View** from the view toolbar to see the part from the top.





STEP 8: SAVE THE GEOMETRY

File

➤ **Save as**

➤ **File Name:** "Your Name_5"

➤ Select the **OK** button.



Mill X²


TOOLPATH CREATION

STEP 9:

SET UP THE STOCK TO BE MACHINED.

Machine type

- Mill
- Select Default.
- To display the Toolpaths Manager press Alt + O.




- Select the plus in front of Properties to expand the Toolpaths Group Properties.

Select the plus




- Select Stock setup.

Select Stock setup




Mill X²


- The stock shape should be set to **Cylinder**.
- Enable the **Z-Axis**.
- Enter the **Diameter** and **Z** values of the stock size.
- Enable **Display stock as Wireframe** and enable **Fit Screen** to the stock.
- Change the **Z** value in the **Stock origin** to set the datum at the top of the part.



- Select the **Tool Settings** tab to set the tool parameters and the part material.
- Change the parameters to match the following screenshot.

🔗 For more information on the **Tool Setting parameters** check **Tutorial #1**.




- Select the **OK** button to exit **Toolpath Group Properties**. 

- Select the **Isometric View** from the view

toolbar to see the stock.



- Select the **Top View** from the view toolbar to see the part from the top.




Mill X²

STEP 10: POCKET AND ISLAND FACING.

Toolpaths


➤ Pocket Toolpath

- Select the **OK** button to accept the **NC** name.
- Select the two chains as shown below.





Select the first chain here


Select the second chain here



- Select the **OK** button to exit **Chaining**.
- Click on the **Select library tool** button.
- Select the **Filter** button in the **Tool Selection** window.



- In the **Tool Types** field select the **None** button to disable all tools.
- Select the **Flat Endmill** button as shown.
- In the **Tool Diameter** field click the pull-down arrow and select **Equal**.
- Enter the tool diameter value.
- Select the **OK** button to exit **Tool List Filter**.




Mill X²

- Make sure that the tool is selected (highlighted) in the **Tool Selection** window.
- Select the **OK** button to exit the **Tool Selection** window.




- Make the changes as shown in the screenshot.

- ☛ The **Feed rate**, **Plunge rate**, **Retract rate** and **Spindle speed** are based on the tool definition. Change them as desired.



- Change the parameters in the **Pocketing parameter** page as shown.


Clearance value sets the height at which the tool rapids to or from the part. **Retract** value sets the height the tool rapids/feed-rates up to, before the next step down. **Feed plane** as an incremental value sets the height the tool rapids to before changing to the plunge rate. **Depth** value sets the final machining depth for the pocket operation.





- Select the drop-down arrow in the **Pocket type** and choose **Island facing**.
- Select the **Facing** button and change the parameters as shown.

Mill X²


- Set the **Overlap percentage** (percentage of the tool diameter) to set the amount the toolpath overlaps the island.
- The **Overlap amount** will be automatically updated.
- Enter the **Approach & Exit distance** values to set the distance from the island to the starting/ exit point in the facing.




- Select the **OK** button to exit **Facing**. 
- Enable and select the **Depth cuts** button to set the cut steps along the Z-axis.
- Enable **Use island depth** to set the depth cuts based on the island depth.
- Select the **OK** button to exit **Depth cuts**.



- Select the **Roughing/Finishing parameters** tab.
- Select the **True Spiral** as the **Cutting method**.
- Enable **Spiral inside to outside** to spiral from the center to the pocket wall.




- Select the **OK** button to exit **Pocket parameters**. 
- Select the **Isometric View** from the view toolbar to see

the toolpath.




- Select the **Top View** from the view toolbar to see the part from the top.



STEP 11: CIRCLE MILLING THE INNER BORE.

Tool paths


- **Circle Paths**
- **Circmill Toolpath**
- Select **Entities** in the **Drill Point Selection** dialog box.



Select Entities

- [Select an entity]: Select the 3" diameter arc.

Select this arc




- Select the **OK** button to exit **Drill Point Selection**.
- Click on the **Select library tool** button.
- Use **Filter** and select the **1/2" Flat End Mill** (see **STEP 10** pages 5-10).

Mill X²


➤ Change the parameters as shown in the following screenshots:

- ☛ The **Feed rate**, **Plunge rate**, **Retract rate** and **Spindle speed** are based on the tool definition. Change them as desired.

➤ In the **Comment** field type a comment about the toolpath for future reference.




➤ Select the **Circmill parameters** tab and change the parameters as shown.



➤ Enter the **Depth** = -1.0.

Mill X²


- Enable and select the **Break thru** button.




- Select the **OK** button to exit the **Break through** dialog box.
- Enable and select the **Depth cuts** button to set the cut steps along the **Z**-axis.
- Enable **Keep tool down** to not allow the tool to retract.



- Select the **OK** button to exit the **Depth cuts** dialog box.
- Check the box in front of the **Roughing** button and select it.

 This style creates roughing passes using tangent arcs. The result provides a smooth motion for the tool, a short NC program, and good cleanout. **Stepover** is set as a percentage of the tool diameter. **Helical entry** parameters create the roughing motion tangent to a helical entry.







- Select the **OK** button to exit.
- Select the **OK** button from the parameter screen.

Mill X²

STEP 12: BACKPLOT THE TOOLPATH.

- Click on the **Toolpath Manager** tab to make it active.
- Select the **Select all operations** button.
- Select the **Backplot selected operations** button.
- Make sure that you have the following buttons turned on (they will appear pushed down).
- **Display tool**
- **Display rapid moves**
- Select the **Isometric View** from the view toolbar to see the stock.
- Select the **Play** button.



- Select the **OK** button to exit **Backplot**. 

Mill X²

TOOLPATH VERIFICATION STEP 13: VERIFY.

- Select the **Verify selected operations** button.




- Select the **Configure** button.



- Enable **Use True Solid** to be able, after verifying the part, to rotate and magnify it to more closely to check features, surface finish, or scallops.
- Enable **Change tool/color** to change the color of the cut stock to indicated tool changes in the toolpath.
- Select the **OK** button to exit

Verify Options.




Mill X²

➤ Set the **Verify speed** by moving the slider bar in the speed control bar.



➤ Select the **Machine** button to start simulation.


➤ The finished part should appear as shown in the following picture.



➤ Select the **OK** button to exit **Verify**.


STEP 14: POST THE FILE.

- Make sure that all operations are selected, otherwise:
- Select the **Post selected operations** button from **Toolpath Manager**.
- In the **Post processing** window, make all the necessary changes as shown below.
- Enable **NC file** to keep the NC file assigning the same name as the MCX file.
- Enable **Edit** to automatically launch the default editor.
- Select the **OK** button to continue.



Mill X²

➤ Select the Save button to accept the file name.



➤ To exit the editor click on the red X.

STEP 15: SAVE THE UPDATED MCX FILE.


➤ Select the Save icon.



Mill X²

REVIEW EXERCISE 1.

Student practise. Create the Toolpath for Exercise 1-Tutorial 5 as per the instructions below;



☞ Tips:

Stock size use **Bounding box** to establish X & Y sizes and give Z = 0.25"

Tool Settings use the same settings as in the tutorial.

Center drill the holes using 1/2" Center drill

Drill the thru holes using 3/4" Drill

Pocket the part using 3/4" Flat End Mill

Use Parallel spiral cutting method



Contour the part using 1.5" Flat End Mill

1 roughing passes with spacing = 0.5"

1 finish pass 0.05" (Multi passes)

Backplot and **Verify** the toolpaths.

Post process the file.



TITLE TUTORIAL 5 - EXERCISE 2


MATERIAL ALUMINUM T6061

DATE: JUNE 12, 2000 eMastercam.com

Mill X²

REVIEW EXERCISE 2.

Student practise. Create the Toolpath for Exercise 2-Tutorial 5 as per the instructions below;



Tips:

Stock size use **Bounding box** to establish X & Y sizes and give Z = 0.75"

Tool Settings use the same settings as in the tutorial.

Center drill the hole using 1/2" Center drill

Drill the thru hole using 3/4" Drill

Circle mill the 2" diameter thru hole using 3/4" Flat End Mill

Use depth cuts; max rough step = 0.375; keep tool down.

Enable roughing

Contour the part using 1.5" Flat End Mill

1 roughing passes with spacing = 0.1"

1 finish pass 0.05" (Multi passes)

Contour remachining the part using 0.375" Flat End Mill

Change the contour type to **Remachining** and set the parameters as shown.


Use Depth cuts; max rough step = 0.25

1 roughing passes with spacing = 0.1"

1 finish pass 0.05" (Multi passes)

Backplot and **Verify** the toolpaths.

Post process the file.



TUTORIAL SERIES FOR

Mastercam.X²

TUTORIAL 6 LEVEL 1 – FACING, CONTOURING, POCKETING, DRILLING, IMPORT FROM LIBRARY.



Objectives:

The Student will design a 3-dimensional wireframe drawing by:

- Creating a rectangle.
- Creating parallel lines.
- Creating fillet radii.
- Creating arcs.
- Using Translate to create a 3-dimensional wireframe.



The Student will create a 2-dimensional milling toolpath consisting of:

- Facing the top of the part.
- Machining 2 simultaneous pockets with different depths.
- Machining a 2D contour.
- Lead in and lead out toolpath entry.
- Importing from the library 9/16 tap holes.
- Drilling 3/8 holes.

The Student will check the toolpath using Mastercam's Verify module by:

- Defining a 3-dimensional block larger than the size of the workpiece.
- Running the Verify function to machine the part on the screen.

ALL DIMENSIONS IN INCHES




TITLE	TUTORIAL 6
MATERIAL	ALUMINUM T6061
DATE:	JUNE 12, 2006
	eMastercam.com

GEOMETRY CREATION

Setting the toolbar states

- Before starting the geometry creation we should customize the toolbars to see the toolbars required to create the geometry and machine a 2D part. See **Getting started** page A-5 in the **User Notes**.
- **Toolpaths/Solids manager** to the left of the screen can be hidden to gain more space in the graphic area for design. Press **Alt + O** to remove it.
- Before starting the geometry make sure that the **Grid** is enabled. It will show you at each moment where the part origin is. See **Getting started** page A-5 for details.



STEP 1: CREATE THE OUTSIDE PROFILE.

1.1 Create a rectangle knowing the width, the height and the base point.


Create

- **Create Rectangular Shapes**
- Select the double arrow to expand the **Rectangle Options** as shown (if needed).
- Type the **Width** the **Height** and the **Fillet Radius** as shown in the picture to the right.

Select the double arrow

Select this radio button

- Select the lower left corner radio button as the anchor.




Mill X²

- [Select position for the base point]: Select the center location of the grid (the origin).

Select the center of the grid

Select position of first corner



- Select the **OK** button to exit the rectangle dialog box.



- Select the **Fit** button to fit the geometry to the screen.



- * During the geometry creation of this tutorial, if you make a mistake you can use the **Undo** icon to undo the last step. You can undo as many steps as needed. If you delete or undo a step by mistake, just use the **Redo** icon.


STEP 2:
CREATE THE FIRST POCKET.
2.1 Create parallel lines.

Create



➤ **Line**


➤ **Create Line Parallel**

- [Select a line]: Select Entity A.
- [Select the point to place a parallel line through]: Pick a point to the right of the selected line.
- Type the **Distance** 1.0 (Enter).
- [Select a line]: Select Entity A.
- [Select the point to place a parallel line through]: Pick a point to the right of the selected line.
- Type the **Distance** 3.0 (Enter).
- [Select a line]: Select Entity A.
- [Select the point to place a parallel line through]: Pick a point to the right of the selected line.
- Type the **Distance** 4.5 (Enter).
- [Select a line]: Select Entity B.
- [Select the point to place a parallel line through]: Pick a point above the selected line.
- Type the **Distance** 0.4 (Enter).
- [Select a line]: Select Entity B.
- [Select the point to place a parallel line through]: Pick a point above the selected line.
- Type the **Distance** 3.0 (Enter).
- [Select a line]: Select Entity B.
- [Select the point to place a parallel line through]: Pick a point above the selected line.



Mill X²


- Type the **Distance**  6.0 (Enter).
- Select the **OK** button to exit the command. 
- The drawing should look as shown in the picture to the right.




2.2 Create the corner fillets.

Create

- **Fillet**
- **Fillet Entities**


- Enter the fillet **Radius**  0.125.
- [Select an entity]: Select Point A.
- [Select another entity]: Select Point B.

☛ Note that a fillet option will be automatically drawn depending on where you move the cursor around the entities.




- [Select an entity]: Select Point C.
- [Select another entity]: Select Point D.
- [Select an entity]: Select Point E.
- [Select another entity]: Select Point F.
- [Select an entity]: Select Point G.
- [Select another entity]: Select Point H.
- [Select an entity]: Select Point K.
- [Select another entity]: Select Point L.
- [Select an entity]: Select Point M.
- [Select another entity]: Select Point N.
- The drawing should look as shown in the picture to the right.


- Select the **OK** button. 





STEP 3:
CREATE THE SECOND POCKET.
3.1 Create parallel lines.



Create



- **Line**
- **Create Line Parallel**
- [Select a line]: Select Entity A.
- [Select the point to place a parallel line through]: Pick a point to the right of the selected line.
- Enter the **Distance**  6.0.


- [Select a line]: Select Entity A.
- [Select the point to place a parallel line through]: Pick a point to the right of the selected line.
- Enter the **Distance**  7.5

- [Select a line]: Select Entity A.
- [Select the point to place a parallel line through]: Pick a point to the right of the selected line.
- Type the **Distance**  9.0.

- [Select a line]: Select Entity B.
- [Select the point to place a parallel line through]: Pick a point above the selected line.
- Type the **Distance**  0.4.

- [Select a line]: Select Entity B.
- [Select the point to place a parallel line through]: Pick a point above the selected line.
- Type the **Distance**  3.5.
- Select the **Apply** button to continue, 

- [Select a line]: Select Entity B.
- [Select the point to place a parallel line through]: Pick a point above the selected line.
- Type the **Distance**  5.0.
- Select the **OK** button to exit the command, 





Mill X²

3.2 Create the corner fillets.

Create

- **Fillet**
- **Fillet Entities**

- Enter the fillet **Radius**  0.125.
- [Select an entity]: Select Point A.
- [Select another entity]: Select Point B.




- [Select an entity]: Select Point C.
- [Select another entity]: Select Point D.


- [Select an entity]: Select Point E.
- [Select another entity]: Select Point F.

- [Select an entity]: Select Point G.
- [Select another entity]: Select Point H.

- [Select an entity]: Select Point K.
- [Select another entity]: Select Point L.

- [Select an entity]: Select Point M.
- [Select another entity]: Select Point N.

- Select the **OK** button to exit the command, 
- The drawing should look as shown to the right:



Mill X²

**STEP 4:
CREATE ARCS KNOWING THE DIAMETER AND THE CENTER POINT.**

Create






➤ **Arc**

➤ **Create Circle Center Point**

➤ Enter the **Diameter** value  9/16 (Enter).

➤ [Enter the center point]: Select the **Fast Point** icon. 

➤ Enter the coordinates: 0.5, 6 (Enter).

●* To create more arcs with the same diameter click on the diameter icon . The diameter and radius values will be highlighted in red.    

➤ Select the **Apply** button to continue, 


➤ [Enter the center point]: Select the **Fast Point** icon. 

➤ Enter the coordinates: 9, 0.5.

➤ Select the **Apply** button to continue, 

➤ Enter the **Diameter** value  3/8 (Enter).

●* Note that the diameter and radius values will still be highlighted in red.

➤ [Enter the center point]: Select the **Fast Point** icon. 

➤ Enter the coordinates: 0.5, 0.5.

➤ Select the **Apply** button to continue, 

➤ [Enter the center point]: Select the **Fast Point** icon. 

➤ Enter the coordinates: 9, 6 (Enter).

➤ Select the **OK** button to exit. 

**STEP 5:
CREATE THE 3-D DESIGN.**

Xform



➤ **Xform Translate**

➤ [Select entities to translate]:

➤ Hold-down the shift key and select Entity A as shown.

●* Note that the entire rectangle is highlighted.


➤ Select the **End Selection** button.



Mill X²


- Enable **Join**.
- Set the number of translations to # 1.
- Change the **Delta** value on Z to -1.0.

- Select the **Apply** button to continue.




- [Select entities to translate]: Hold-down the Shift key and select Entity B.
- * Note that the entire pocket is highlighted.

Entity B




- Select the **End Selection** button.
- Enable **Join**.
- Set the number of translations to # 1.
- Change the **Delta** value on Z to -0.25.

- Select the **Apply** button to continue.




Mill X²

- [Select entities to translate]: Hold-down the Shift key and select Entity C.
- * Note that the entire pocket is highlighted.



- Select the **End Selection** button.



- Change the **Delta** value on **Z** to -0.125.



- Select the **OK** button to exit.



Screen

- **Clear colors**

- Select the **Isometric View** from the view toolbar to see the stock.




- Select **Fit** button.



STEP 6: SAVE THE GEOMETRY

File

- **Save as**
- **File Name:** "Your Name_6"
- Select the **OK** button.




Mill X²

**TOOLPATH CREATION
MACHINE THE TOP OF THE PART**

STEP 7:

SET UP THE STOCK TO BE MACHINED.

- Machine type
- Mill
- Select Default.
- To display the **Toolpaths Manager** press **Alt + O**.



- Make sure that **3D** mode is enabled in the **Status Bar**.
- Select the plus in front of **Properties** to expand the **Toolpaths Group Properties**.




- Select **Stock setup**.

Select the plus





Select Stock setup




Mill X²


- Select the **Bounding box** button as shown.

 The **Bounding box** function automatically finds the extents of the part based on the part geometry.




- Expand the X, Y and Z sizes with 0.1
- * The size of the blank material will be the finish size plus 0.2" on width, length and on thickness
- Select the **OK** button to exit the **Bounding Box** dialog box. 



- Make sure that you have the same parameters as shown in the following screenshot.



Mill X²


- Select the **Tool Settings** tab and change the parameters to match the screenshot to the right.
- ☛ For more info on parameters see Tutorial #1.




- Select the **OK** button to exit **Toolpath Group Properties**. 
- Use the **Fit** icon to fit the drawing to the screen. 

STEP 8: FACING THE TOP OF THE PART.


Toolpaths

- **Face Toolpath**
- Select the **OK** button to accept the **NC file name**.
- [Select OK to use defined stock or select chain1]:
- Select the **OK** button to use defined stock. 




Mill X²

➤ Right-mouse click in the **Toolpath parameters** and select **Create new tool**.




➤ Select **Face Mill** in the **Tool Type** as shown.




➤ Change the **Diameter** to 3.0" and the **Outside dia** to 3.5", and press Enter.

➤ The **Facing** dialog box should look as shown in the screenshot to the right.




Mill X²

- Select the **Parameters** tab and make the changes as shown to the right.
- Type in the **Tool name** field: **3" Face Mill**.



☛ The tool will be available just for the current job. To save the tool in a library select **Save to library** button .

- Select the **OK** button to close **Define tool** dialog box. 
- Change the parameters in the **Toolpath Parameters** page as shown.



Mill X²

- Select the **Facing parameters** page and change the parameters as shown.
- Select the drop-down arrow and change the **Move between cuts** to **Linear**.




Clearance value sets the height at which the tool rapids to or from the part.

Retract value sets the height the tool rapids/feed-rates up to, before the next step down.

Top of stock value sets the height of the stock in the Z-axis. It is based on the job setup values.

Depth value sets the final machining depth for the facing operation.




- Select the **OK** button to exit.




STEP 9: ROUGH CUTTING THE TWO POCKETS.

Toolpaths

- **Pocket Toolpath**
- Enabled **C-plane** in **Chaining** to be able to select the chains without stopping at the branches.
- Select the two pockets at the bottom, as shown.




- ☛ Note that the entire pockets are highlighted.
- Select the **OK** button to exit **Chaining**.




Mill X²


➤ Click on the **Select library tool**.





➤ Select the **Filter** button in the **Tool Selection**.




➤ In the **Tool Types** field select the **None** button to disable all tools.




- Select the **Flat Endmill** tool type as shown (upper right corner).
- In the **Tool Diameter** field click the pull-down arrow and select **Equal**.
- Enter the **Tool Diameter** value to 1.0.
- Select the **OK** button to exit **Tool List Filter**. 
- Make sure that the tool is selected (highlighted).
- Select the **OK** button to exit the **Tool Selection** dialog box. 

➤ Make the necessary changes to match the parameters with the screenshot to the right.



➤ Select the **Pocket parameters** page and change the parameters as shown.



Depth value sets the final machining depth for the pocket operation. The value is set to 0 and **incremental** and is measured from the two geometry chains that we selected. This insures that both of them are going to be machined to the appropriate depth. Choosing **Incremental** tells the system to calculate the value relative to either the current top of stock (as with **Clearance** parameter), relative to the selected geometry (as with **Top of stock** and **Depth** parameters), or relative to the depth of each cut (as with **Feed plane** and **Retract**).


Mill X²


- Select the **Roughing/Finishing parameters** tab.


 **Stepover percentage** sets the distance between roughing passes in the XY axis as a percentage of the tool diameter and will automatically update the stepover distance.

Spiral inside to outside enabled allows you to spiral from the center to the pocket wall.


 **Finish area** enabled allows the tool to make another cut around the pocket walls to “contour” them.



- Select the **Constant Overlap Spiral** as the **Cutting method**.
- Disable the **Finish** area.
- Select the **OK** button to exit **Pocket parameters**. 




**STEP 10:
RE-MACHINING THE TWO POCKETS.**

-  Note that the 1.0” Flat End Mill could not clean the 0.125” radius fillets. Using a 1/8” Flat End Mill to remove all the material inside the pocket will not be efficient. We will remove the remaining material using an 1/8” Flat End Mill tool with the remachining pocket style.
- Select **Toolpath Manager**.
- **Right-mouse click** and hold it down on the folder icon in front of the **Pocket** toolpath.
- Drag the mouse down and release it.
- Select **Copy after**.




Mill X²

- You should now have two pocket toolpaths.
- Left-click on the second pocket **Parameters**.




Select Parameters

- Select the **Toolpath parameters** page.
- Click on **Select library tool**.
- Following the steps outlined earlier, using the **Filter** option, select the **1/8" Flat End Mill**.




- Select and change the parameters in the **Pocket Parameter** dialog boxes, as shown below.



Mill X²

- Select the drop-down arrow in the **Pocket type** field and select **Remachining**.
- Select the **Remachining** button and match the parameters with the following screenshot.



 **Compute remaining stock from The previous operation** enables the system to calculate the remaining stock for remachining by determining the stock left after the previous operation.


Clearance, set as a percentage of the tool diameter, allows you to expand the remachining area at the beginning and at the end to prevent a cusp of material remaining.

Apply entry/exit curves to rough passes allows you to use the Lead in/out parameters.


Machine complete finish passes allows you to finish the entire part.



- Select the **OK** button to exit. 
- Select the **Depth cuts** button and change the parameters as shown.
- Select the **OK** button to exit. 



- Check the parameters in the **Roughing/finishing parameters** page to match the following screenshot.



- Select the **OK** button to exit. 