



ASSIGNMENT_0

CIVI SITE ANALYSIS


LOCATION: 543 MAIN ST, NEW YORK, NY 10044
 ZONNING DIVISION: R7-2,C4-5 R= RESIDENT C= COMMERCIAL



- F TRAIN
- BUILDING FOOTPRINT
- PARK
- ROADS



LIGHTING IS POORLY DISTRIBUTED. THREE LAMP POST DUE TO HISTORICAL VAULE UNDERMINE THE SPACE'S NEED TO BE MORE WELL LIGHT. SPACE IS INEFFECTIVE AFTER SUNSET.



OPEN SKYVIEW OVERHEAD MAKES THE SPACE FEEL MUCH BIGGER THAN IT IS.

MAIN STREET IS A SOURCE OF AUDIO DISTURBANCE SINCE THERE IS NO NATURAL ACCOUSTICAL INSULATION DUE TO THE OPEN SPACE AROUND THE CRHURCH.