



Each crosscut for the MDO should be 1-3/16" on the table saw with a cross cutting Jig.
 Tablesaw should be set to 3" on the blade before cutting.
 A circular jig should be used as a reference to bend the MDO.
 For gluing the MDO to shape the kerf bend, use a combination of multi-purpose glue and sawdust to glue in the gaps.

NYC COLLEGE OF TECHNOLOGY	
ENT 4410 - Technical Direction	
Kerf Bend Test Piece Top and Back View	PLATE NO.
DRAWING PRACTICE WORKSHEET	1
SCALE: 3" - 1'-0"	
DATE: 3/22/2023	
DRAFTER: Charles Mandell	OF: 10