


# Space Analysis & Program Review/Mechanical Review

FROM THE CAFE, IS THE KITCHEN WHICH HAPPENS TO BE SMALL, BUT ALSO A PATH INTO THE GARDEN THAT LEADS INTO THE ROCKWALL

FROM THE LOBBY, IS WHERE THE POOL IS LOCATED, CONNECT TO THE GARDEN, AND THE CAFE

WITH THE LOBBY, WHICH IS CONNECTED TO THE STUDIO, BUT ALSO LEAD BY THE LOBBY, WHICH IS LEAD WITH A CORRIDOR THAT CONNECTS TO THE CAFE,




FIRST FLOOR, PROGRAM CONSIST OF CAFE, KITCHEN, POOL, LOBBY, ROCKWALL, AND STUDIO

01 GROUND FLOOR PLAN

THE HEALTH CLUB DESIGNED TO WHERE THERE IS DOUBLE HEIGHT SPACE, ABOVE THE FIRST FLOOR POOL, THERE IS NO EXISTING PROGRAMS


THE OFFICE IS NEAR THE STAIRCASE, AND ELEVATOR, BUT HOWEVER THE SIZE OF THE OFFICE DOESN SEEM SMALL,

THE ROCKWALL CONTINUING TO THE SECOND LEVEL, THE EXERCISE STUDIO IN LOCATED BETWEEN THE TWO STAIRWELLS, HOWEVER TO THE TOP STAIR THE CORRIDOR DOES SEEM NARROW,



SECOND FLOOR, BEING ONLY A L-SHAPED, CONTINUING WITH THE ROCKWALL, AND EXERCISE STUDIO, AND OFFICE

02 2nd FLOOR PLAN




2 -1/2 FLOOR, IS THE FLOOR IN BETWEEN THE 2ND AND THIRD FLOOR,, WITH THE EXERCISE ROOM

03 2.5 EXERCISE ROOM

SIMILAR TO THE SECOND FLOOR, THE THIRD FLOOR RETURN TO THE L-SHAPED DESIGN,

THE THIRD FLOOR CONTUUES WITH THE ROCK WALL, AND EXERCISE STUDIO

THE OFFICE IS ALSO LOCATED, ON THE THIRD FLOOR AS WELL AS THE SECOND FLOOR




04 3rd FLOOR PLAN

1/8" = 1'-0"



THURD FLOOR, SIMILAR TO THE SECONDD FLOOR, HAS THE L- SPAPED DESIGN WITH THE ROCKWALL, AND THE EXERCISE STUIIOD, & OFFICE




THE FOURTH FLOOR CONTUUES WITH THE ROCK WALL, AND EXERCISE STUDIO

THE OFFICE IS ALSO LOCATED, ON THE FOURTH FLOOR AS WELL AS THE SECOND FLOOR

FOURTH FLOOR, IS THE REPATED OF THE SECOND & FOURTH FLOOR DESIGN AND PROGRAM LAUOUT

05



06 LOCKER ROOM PLAN

1/8" = 1'-0"

THE LOCKER ROOM HAS MIN. EXIT POINTS TO GET OUT,

THE MECH. ROOM IS VERY SMALL TO ACCOMIDATE THE BUILDING OF THAT SIZE, ALSO WITH THE POOL THERE SHOULD BE A FILER ROOM PRESENT,

LOCKER ROOM PLAN, ALSO WITH THE LAUNDRY ROOM, AND MECH. ROOM,

THE POOL BEING RIGHT ABOVE THE LOCKER ROOM, THE POOL ISNT INCIATED ON THE PLAN,

THE LOCKER ROOM, HAS VERY SMALL CORRIDOR LEADING IN AND OUT THE ROOM,