

1 Back Staircase - Top View

1

Notes:


Framed with $\frac{1}{3}$ " Plywood

Skinned with $\frac{3}{4}$ " A/C Plywood

Risers and Threads are to be stapled and glued to the sides.

Must have an 8" landing to prevent tripping hazard.

Railing must be included.



2 Back Staircase - Section View

2

Notes:

Framed with $\frac{1}{3}$ " Plywood

Skinned with $\frac{3}{4}$ " A/C Plywood

Risers and Threads are to be stapled and glued to the sides.

Must have an 8" landing to prevent tripping hazard.

Railing must be included.

NYC COLLEGE OF TECHNOLOGY

ENT 4410 Technical Direction

Back Staircase - Section/Top View

PLATE NO.

DRAWING PRACTICE WORKSHEET

1

SCALE: $\frac{3}{4}$ " = 1'-0"

DATE: 2/15/2023

DRAFTER: Tristen Weber

OF: 1